



Metallic Application - Cleaning Tips & Instructions

Thank you for choosing Concrete Science! Enclosed are cleaning and maintenance instructions for your new flooring. Following these instructions will ensure proper care and extend the life of your floor.

For regular cleaning of your floor coating, a soft-bristled broom, dust mop or a microfiber mop will work great! Using your broom or mop once a week is the best way to gather loose dust or dirt and to keep your floor looking its best! Any spills that occur should be removed within the first 24 hours to avoid staining.

Metallic floors can be mopped with water only, changing the water when needed. We recommend a hard foam mop as a string mop may leave streaks and may not clean the floors efficiently.

Windex containing ammonia should leave your floor residue and streak free.

Do not use heavy degreasers, detergents, abrasive cleaners (AJAX), solvents or acids to clean the floor.

Do not allow cleaning products to dry on the application surface.

Try not to drag furniture, Rubbermaid totes or other sharp items on the floors – this can cause scratches in the topcoat application.

Additional coats of Carefree Floor Finish can be applied for an additional charge. Carefree Floor finish helps mitigate floor scratching and other minor surface marks. We do recommend that this application be applied once per year for our residential customers, 3-4 times per year for commercial customers, where heavy traffic is present.

We hope you love your new floor and appreciate your business! If you have any questions regarding the cleaning or maintenance of your new floor, please give us a call at 763.420.4073.